

Gus, Turning the Model Garage into a Laboratory, Works Out Easy Formula for Radiator Solutions



"Paste this in your hat," Gus suggested. "A glycerin solution that floats this particular hydrometer at 1,080 will keep Jack Frost out of your radiator down to ten degrees."